

Cross Check™

Torque Seal® Tamper-Proof Indicator Paste

HANDLING

- Obtain special instructions before use.
- Do not handle until all safety precautions have been readand understood.
- Do not handle, store or open near an open flame, sources of heat or sources of ignition.
- Protect material from direct sunlight. Explosion-proof

DIRECTIONS

- DRY TIME: Dry to touch/handle in 30-40 minutes.
- 80% curing occurs between 48-72 hours. Completion of curing takes place between 7-10 days.
- Exposing to elevated temperature OR blowing hot are can speed up the drying/curing process.

STORAGE

• Store locked up. Keep away from heat, sparks and open flame. Prevent electrostatic chargebuild-up by using common bonding and grounding techniques. Store in a cool, dry place out ofdirect sunlight. Store in original tightly closed container. Store in a we

DISPOSAL

 Collect and reclaim or dispose in sealed containers at licensed waste disposal site. Dispose of contents/container in accordance with local/regional/national/international regulations.

FEATURES

- Tamper Proof Torque Mark
- Safe for most surfaces
- Highly visible- blue, yellow, red, green, and orange colors are fluorescent
- Excellent adhesion
- · Visually detects loose nuts & bolts
- Provides warranty protection
- Meets BOEING Specification, BMS8-45 Type II



PHYSICAL PROPERTIES

Appearance / Physical State	Liquid	
Odor	mild	
Flash Point	105.1 °F (40.6 °C)	
Boiling Point / Range	276.98 - 485.06 °F (136.1 - 251.7 °C	
VOC Content	42.28%, 430 g/L	
Vapor Density	> 1 (air = 1)	
Prop 65 Warning	YES	

AVAILABLE IN

Color	Net	Containe	Units/Ca	Part #	
				US	Canada
	Contents	r Type	se		
orange	1 oz	tube	24	83314	C83314
green	1 oz	tube	24	83315	
red	1 oz	tube	24	83316	C83316
yellow	1 oz	tube	24	83317	C83317
blue	1 oz	tube	24	83318	C83318
white	1 oz	tube	24	83319	C83319
pink	1 oz	tube	24	83320	C83320
gray	1 oz	tube	24	83321	

